



MEDIAN DEFICIENCIES

Disclaimer Statement:
This is not a proposal

This is a display of median deficiencies if strict Interstate standards were applied.
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.

Tag #	CO	PM	Location Description
1	SJ	2.660/6.390	.1 mi n of SB off to Jack Tone-.1 mi s of SB on from Yosemite/120
2	SJ	0.000/1.900	Stanislaus/San Joaquin County Line-Milgeo Ave OC Br (29-185)
3	STA	R24.380/R24.750	NB on from Hammett Rd-Stanislaus/San Joaquin County Line
4	MER	8.787/T12.740	Lingard Rd-Beginning of temp section
5	MER	0.000/2.479	Madera/Merced County Line-.1 mi s of Dutchman Cr (39-01)
6	MAD	28.615/29.360	.7 mi s of Chowchilla Riv (41 1)
7	MAD	17.850/17.861	Berenda Creek (41 4)
8	MAD	R7.850/9.740	SB off Ave 12-South Madera OC (41 46)
9	MAD	4.100/4.800	1-1.7 s of Little Dry Cr (41-35)
10	MAD	0.000/R0.410	Fresno/Madera County Line (San Joaquin River Br)
11	FRE	20.270/26.240	NB on from Ventura Ave-.02 n of Dakota Ave OC (42-148)
12	TUL	52.300/52.800	.3 mi s of Kings River Br (46-36)-Mendocino Ave OC (46-199)
13	TUL	33.330/33.960	SB off to Tulare-NB off to Ave 264
14	TUL	18.150/21.430	SB on to Rte 190-Tule River Br (46 56)
15	KER	52.450/54.480	Pond Rd OC (50-234)-Woollomes Ave OC (50-210)
16	KER	R47.750/49.300	.2 mi n of SB off to Whisler Rd-Sherwood Ave OC (50-223)
17	KER	44.310/R46.950	Rte 46/99 Separation (50-184)-.5 mi s of SB off to Whisler Rd
18	KER	R41.570/R43.420	.2 mi s of Poso Cr Overflow (50-180)-Famoso OH (50-11-LT)
19	KER	R31.180/R39.120	SB off to 7th Standard Rd-Merced Ave OC (50-179)
20	KER	L0.000/10.770	.6mi s of 5/99 separation-.2 mi s of old US99 OC (50-238)

